(Task #4271)

Bond Release Findings

August 11, 2011

Mine Name:	Maynard Topaz	I.D. No.: S/023/0099	
Operator:	Colorado Calumet Co. Inc.	Mineral Ownership: SITLA	
		Surface Ownership: SITLA	

Disturbed and Bonded Area: 3 Acres

Acres Requested for Partial Release: 3 Acres Acres to be Release with this Action: 3 Acres, partial bond release – 3 year vegetation requirement.

0	Name of Street	
3	u	rety

Total Surety Amount: \$15,400.00 Form: Cash
Amount Requested for Release: \$15,400.00
Amount Recommended for Released: \$11,400.00

Operations:

The Division received an application for bond release on July 27, 2011. According to the 2010 annual report, the site was reclaimed in the late spring of 2010.

Reclamation

<u>General</u>: According to the 2010 annual report, the site was reclaimed in the late spring of 2010. The Operator completed backfilling and regrading. Seeding was done in the late spring of 2010.

<u>Public Safety</u>: There were no shafts or adits at the site. The highwalls have been backfilled and regarded. There are no public safety features on site.

Slopes, Highwalls, and Pits: All highwalls have been reclaimed to slopes of less than 45 degrees.

Plugging of Drill Holes and Closing Adits, Shafts, Etc.: No such structures on site.

<u>Dams, Impoundments, and Drainages</u>: No dams or impoundments on site. The drainage is controlled by backfilling and grading in addition, vegetation once established should also control erosion

<u>Roads</u>: There were no true roads on the site. Vehicles moved over the pad area as needed. There is a road to the site that is off the permit area and was not reclaimed.

Revegetation. There is little vegetation on the reclaimed area.

Recommendation

The Division should do a partial bond release for the site. The Division should maintain a minimum of \$4,000.00 to ensure vegetation success.

Way Waters Permit Load

 $O: \label{local-decomposition} O: \label{local-decomposition$